Appendix C

HAZARD MANAGEMENT – SAFE OPERATING PROCEDURE (SOP)

Only to be completed where required as a control measure under a Risk Assessment

NAME OF THE TASK/ACTIVITY	LEICA VT1200 AND VT1200S VIBRATING BLADE MICROTOME (VIBRATOME)	DATE: 13/02/2020
LOCATION	LEICA VT1200 WAITE CAMPUS BUILDING 19 ROOM G10 LEICA VT1200S NT CAM	