Residual risk rating on the RA	Low	Medium	High	Very High	
Hazards identified on the RA	Contact with 6	electricity or pot	ential for electri	ic shock	
This Safety information should be provi	ded to new users for	or them to read be	fore undertaking	and tasks/activi	ities on the microscope.
Pre-operational checks					•
·					
Operational checks/steps to complete tl	he activity from sta	rt to finish (includ	ing transport and	d waste disposal	where relevant)
	•				
All new users must have a	nractical demo	nstration of the	operation of	the machine f	from a member of
Adelaide Microscopy staff.	practical defilo	istration or the	operation of	the machine i	iroin a member or
Users should operate the in	nstrument in ac	cordance with	the manufacti	ırar sunnliad	anarating instructions
to avoid damage to the inst		cordance with	the manufacte	arei supplieu	operating instructions
The user operable parts are		from the oners	tor's consola	usars of the	instrument should not
attempt to remove any fixtu				, users or the	IIISH UITICHL SHOUIU HOL
Users should not access th			pe.		
USEIS SHOULD HOL access to	ie rear or the in	<u>strument.</u>			
On completion of work – steps to make	safo (including clo	an un anv wasto	lienosal & convic	o/maintonanco r	aquiraments)
On completion of work – steps to make	sale (including cle	an up, any waste t	iisposai a sei vic	e/maintenance n	equirements)
Emergency and Spill Procedures, Trans	sport or storage red	juirements (where	relevant), First a	id/Medical	
Prepared by					
	<del>                                     </del>				

HSW Handbook	Hazard Management	Effective Date:	17 December 2019	Version 3.0
Authorised by	Chief Operating Officer (University Operations)	Review Date:	17 December 2022	Page 1 of 1